
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/15/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S05SS_002MH	Test ID: <u>D1032-015005</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S05SS_002MH
0			Water Level	
17.20000076			Dye Test Visible	@ IR, 2 GPM
17.20000076	09		Infil Runner	@ jt
20.29999924			Dye Test Visible	@ IR, 1/2 GPM
20.29999924	07		Infil Runner	@ jt
22.29999924			Abandoned Survey	NO MORE DYE VISIBLE